MEMORANDUM

To: STACK TEST FILE – STERICYCLE

Through: Bryce C. Bird, Air Standards Branch Manager

From: Harold Burge, Major Source Compliance Section Manager

Date: 2/21/2007

Subject: COMPANY: STERICYCLE

CONTACT: MILES HANSEN (936-1171)

LOCATION: 90 N. 1100 W., NORTH SALT LAKE, DAVIS CO., UT

TEST CONTRACTOR: CUSTOM STACK ANALYSIS
SOURCE: MEDICAL WASTE INCINERATOR

AIRS #: 01100055

PERMIT #: 1100055001 REVISED 10/23/2003

ACTION CODE: 3A

SUBJECT: REVIEW OF STACK TEST REPORT DATED 12/27/2006 & ADDITIONAL

INFORMATION RECEVIED 2/20/2007

FINDINGS:

On 12/27/2006 DAQ received a stack test report for the Medical Waste Incinerator. Additional information was received on 2/20/2007. Testing was performed on 10/18/2006 to demonstrate compliance with the emission limits referenced in Permit Condition II.B.4.c and to establish new operating parameters in accordance with Permit Conditions II.B.4.c.1. The DAQ-calculated test results are:

<u>Source</u>	Test Date	<u>Pollutant</u>	Result	<u>Limit</u>
Medical Waste Incinerator	10/18/2006	PM	2 mg/dscm	34 mg/dscm
		СО	@ 7% O ₂ 20 ppmdv	@ 7% O ₂ 40 ppmdv
			@ $7\% O_2$	@ $7\% O_2$
		Dioxin/furan	2 mg/dscm	125 mg/dscm
		D (0 (777.0)	@ $7\% O_2$	@ $7\% O_2$
		Dioxin/furan (TEQ)	0.1 mg/dscm	2.3 mg/dscm
		HCl	@ 7% O ₂ 6 ppmdv	@ 7% O ₂ 100 ppmdv
		TICI	$@7\% O_2$	$@7\% O_2$
		SO_2	6 ppmdv	55 ppmdv
			$@7\% O_2$	$@7\% O_2$
		NO_X	250 ppmdv	250 ppmdv
			@7% O_2	$@7\% O_2$
		Pb	0.004 mg/dscm	1.2 mg/dscm
		C.I	@ $7\% O_2$	$@7\% O_2$
		Cd	0.001 mg/dscm @ 7% O ₂	0.16 mg/dscm
		Нg	0.004 mg/dscm	@ 7% O ₂ 0.55 mg/dscm
		115	$(a, 7\% O_2)$	$(a, 7\% O_2)$

A three-hour VEO of stack emissions was performed during the stack test. No opacities were observed.

Operating parameters established during test:

Max.Charge Rate: 1,985.1 lb/hr
Min. Secondary Chamber Temperature: 1,797.6 F
Max. Reactor Inlet Temperature: 408 F
Min. Carbon Injection Rate: 2.85 lb/hr
Min. Scrubber Liquor Flow Rate: 62.1 lb/hr

Min. Scrubber Liquor pH: 5.98

DEVIATIONS: None noted.

CONCLUSION: At the time of testing, measured emissions appeared to be within limits.

RECOMMENDATIONS: The facility should be considered in compliance with the above-mentioned

emission limits at the time of testing.

Verify that the facility is operating within the above-mentioned operating

parameters during the next inspection.